

Krossi Control Box

Reset Procedure Please note the desk will travel down very

The control unit is now reset to its original setup.

If the above steps are unsuccessful, please complete the below full factory reset.

B. FACTORY RESET

Re e c l b i i g i a l f a c e i g

1a. Press the keys **mem** i i **1,2** and the **de k** ke at the same time. Keep the key combination pressed for about 10 seconds. Then release the keys.

1b. The display will show '**S**' and a number, e.g. '**S 5**' or '**S 3**'

2. Press the desktop **ke** until the display reads '**S 0**'.

3. Press the **a e ke** .

4. Unplug lead from control box or pull out power lead from GPO to remove power supply. Wait 5 to 15 seconds for the control unit screen to clear.

5.